

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-003198**Date Inspected:** 26-Jun-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1400**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 2330**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yan Hua**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG deck panels**Summary of Items Observed:**

Heavy Duty Machine Shop – Bay 3

Caltrans Quality Assurance Inspector George Goulet (QA Inspector) randomly observed ZPMC CWI Sun Wei (CWI) perform a visual inspection (VT) and QA Inspector performed an R2 VT of the repaired closed ribs to deck panel welds on deck panel assemblies DP-025-001, DP-027-001, DP-065-001, DP-067-001, and DP-074-001. QA Inspector agreed with CWI's acceptance and made notation of R2 VT and QA Inspector's acceptance on the yellow tags attached to each above noted deck panels. Ten workers were present in this shop as well as ABF personnel Kevin Chen. No welding was being performed.

Summary of Conversations:

No significant conversations this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ady Velasco, 138-1694-2685, who represents the Office of Structural Materials for your project.

Inspected By: Goulet,George

Quality Assurance Inspector

Reviewed By: Carreon,Albert

QA Reviewer